

CHANGE ORDER NO. 1

March 25, 2019

McCuen Construction, Inc. 645 Antelope Blvd., Suite 14 Red Bluff, CA 96080

Attention:

Frank Gonczeruk, V.P. Northern Division

Subject:

Willows High School Bleacher and HVAC Modernization

Willows Unified School District Architect's Project No.: 2017-1293

You are hereby authorized to make the following changes in the subject work.

Workmanship and materials shall be in accord with standards established by the original specifications.

ITEM NO. 1:

Change wall tile to from 4x4 to 6x6 per CCD2.

Requested by:

Architect

Reason:

Allow tiled design to fit better.

Attachments:

PCO 001R1, CCD 002

Change in Contract Amount

ADD

1,145.10

No Change in Contract Performance Period

ITEM NO. 2:

Additional cost for abatement in the office, staff locker, staff toilet, and

staff shower due to existing 9"x9" tiles per RFI #14.

Requested by:

Contractor

Reason:

Unforeseen Condition. Original tile flooring covered by carpeting.

Attachments:

PCO 02R1

Change in Contract Amount

ADD

4.118.40

ITEM NO. 3:

Cost to add isolation valves to each bathroom due to fact that existing valves do not

work.

Requested by:

Contractor

Reason:

To allow isolation of restroom water without shutting off water to entire Gym building.

Attachments:

PCO 003R1

Change in Contract Amount

ADD

\$

2,994.25

No Change in Contract Performance Period

ITEM NO. 4:

Add and install a second fire smoke damper through the concrete wall as per Response

to RFI #12. The installation will also include a new supply air plenum to supply each fire

smoke damper.

Requested by:

Architect

Reason:

To allow the required air supply to be distributed as designed.

Attachments:

PCO 004, RFI 012.

Change in Contract Amount

ADD

5.729.73

No Change in Contract Performance Period

ITEM NO. 5:

Replace the existing ceiling tiles with rated ceiling tiles at the existing Gymnasium Foyer.

Requested by:

Architect

Reason:

At some point, the original fire rated ceiling tiles were removed and replaced with non-

rated ceiling tiles.

Attachments:

PCO 005.

Change in Contract Amount

ADD

\$

\$

1,261.70

No Change in Contract Performance Period

ITEM NO. 6:

(E) floor cleanouts were not to grade and discovered during trenching operations.

Requested by:

Contractor

Reason:

Unforeseen Condition. The (e) cleanouts were buried below grade.

Attachments:

PCO 009R1.

Change in Contract Amount

ADD \$

1,311.78

ITEM NO. 7: Install joist ledger at the concrete wall of the existing storage room at the Girls locker Rm.

Requested by:

Architect

Reason:

To attach (e) ceiling joists.

Attachments:

COR 017

Change in Contract Amount

ADD

\$

2,119.07

No Change in Contract Performance Period

ITEM NO. 8: Replace existing shower tempering valves at Boys and Girls locker rooms.

Requested by:

Architect

Reason:

Existing valves were corroded and ready to break.

Attachments:

COR 019R1

Change in Contract Amount

ADD \$

6,404.82

No Change in Contract Performance Period

ITEM NO. 9: Delete the west entry ramp from the project.

Requested by:

Owner

Reason:

To be installed at a later date.

Attachments:

COR 20

Change in Contract Amount

CREDIT

\$

(13,990.66)

No Change in Contract Performance Period

ITEM NO. 10: Delete epoxy flooring from the project.

Requested by:

Owner

Reason:

District opted to do this work.

Attachments:

COR 021

Change in Contract Amount

CREDIT \$

(38, 192.00)

March 25, 2019 Change Order No. 1

Willows HS Bleacher HVAC Mod.

Page 4

ITEM NO. 11: CO #22R1 Additional wiring at EMO fixtures Per RFI #041.

Requested by:

Contractor

Reason:

Wiring length requirements for light fixtures not noted on plans.

Attachments:

COR 022R1

Change in Contract Amount

ADD

2,049.45

No Change in Contract Performance Period

ITEM NO. 12: Remove and replace the existing AHU-2 coil and mixing box.

Requested by:

Architect

Reason:

Unforeseen condition. The existing mixing box and coil unit could not work with the new AHU-2 unit. The mixing box would hold condensation and leak down to the band room.

Attachments:

COR 024

Change in Contract Amount

ADD

\$

\$

16,444.59

No Change in Contract Performance Period

ITEM NO. 13: Removal of existing underground transite piping in the boys and girls restrooms.

Requested by:

Contractor

Reason:

Unforeseen condition

Attachments:

COR 025

Change in Contract Amount

ADD

\$

6,192.38

No Change in Contract Performance Period

ITEM NO. 14: Provide additional framing at CCU-2 and CCU-3, per response to RFI 020.

Requested by:

Architect

Reason:

Actual spacing of existing framing varied from as-built plans requiring additional and

revised support framing.

Attachments:

COR 026R1

Change in Contract Amount

ADD

ADD

\$

1,522.70

No Change in Contract Performance Period

ITEM NO. 15: Abate ceiling plaster in Staff Locker/Shower area for new finishes, per RFI #23.

Requested by:

Contractor

Reason:

Not noted on plans

Attachments:

COR 027R1

Change in Contract Amount

No Change in Contract Performance Period

\$

2.493.57

March 25, 2019 Change Order No. 1

Willows HS Bleacher HVAC Mod.

Page 5

ITEM NO. 16:

Remove abandoned HVAC controller at Mechanical/Pool Room, per RFI 15.

Requested by:

Architect

Reason:

Unforeseen condition. Allowed for placement of new electrical panel.

Attachments:

COR 028R1

Change in Contract Amount

ADD

\$

1,104.26

No Change in Contract Performance Period

ITEM NO. 17:

Remove existing concrete curb from south corner of Girls Locker Room.

Requested by:

Contractor

Reason:

Unforeseen condition.

Attachments:

COR 029

Change in Contract Amount

ADD

\$

1,486.89

No Change in Contract Performance Period

ITEM NO. 18:

Remove locker room sitting bench support poles.

Requested by:

Owner

Reason:

Originally, the Owner was to remove this item.

Attachments:

COR 031

Change in Contract Amount

ADD

\$

1,631.33

No Change in Contract Performance Period

ITEM NO. 19:

Revise panic hardware type at doors 101A and 101B to work with existing frames.

Requested by:

Architect

Reason:

Specified panic hardware did not function correctly.

Attachments:

COR 033R1

Change in Contract Amount

ADD

\$

3,636.60

No Change in Contract Performance Period

ITEM NO. 20:

Remove (e) walls and curbs then reframe the walls at Boys 116 & Girls 113 restrooms per RFI #24.

Requested by:

Contractor

Reason:

Contracto

Unforeseen Condition. Once the walls were opened, the new work could not be installed

without removal of these curbs.

Attachments:

COR 035R1

Change in Contract Amount

ADD

\$

12,187.04

ITEM NO. 21:

Remove concrete base under the existing lockers at the coach's restroom at the Boys

and Girls locker room coaches' offices.

Requested by:

Architect

Reason:

Unforeseen condition, hidden by the existing locker system.

Attachments:

COR 036

Change in Contract Amount

ADD

\$

1,344.11

Original Contract Amount	\$ \$	2,850,000.00 0.00 2,850,000.00 22,995.11 2,872,995.11
% Change by this Change Order Total % Change of Original Contract Amount	% %	0.81 0.81
Original Completion Date Revised Completion Date Revised by Previous Change Order(s) Calendar Days added by this Change Order Revised Completion Date through this Change Order		August 8, 2018 August 8, 2018 0 August 8, 2019

The acceptance and approval of this change order constitutes full and final settlement for all work and costs (including extended overhead, inefficiency and impact or delays) related to the items addressed herein with no exceptions.

APPROVED: Willows Unified School District 03/27/2019 ACCEPTED: McCuen Construction, Inc. Date 03/26/2019 APPROVED: Gray Architects Date 03/27/2019 APPROVED: Warren Consulting Engineers. Date ohn O and sun 3/26/2019 APPROVED: Anderson Structural Group Date 03/26/2019 APPROVED: Date Veston & Associates RENEWAL DATE: 3/26/2019 APPROVED: Edge Electrical Consulting PROFESSIONAL PROFESSIONA D. ANDERS i:\1293 willows hs - bleacher hvac mod\6.11 chngordr\co 1\chng THOMAS E. EXP. 12/31/20 **FASSBENDER** No. E 017376

03/26/2019